



ATKINS

Columbus Drive
CORRIDOR REDESIGN

Existing Peak Hour Level of Service (Two-Way Configuration)

MPO METROPOLITAN PLANNING ORGANIZATION FOR TRANSPORTATION